## Cross Country Field Services Shoreline Erosion Project — Killarney, MB

Website:

www.crosscountryfs.ca

Phone:

(204)744-2285

**Email:** 

info@crosscountryfs.ca



## **Project Overview**

For this project, we were engaged to provide a solution to address the ongoing erosion that was taking place along the shoreline of a cottage at Killarney, MB.

The owners were looking for a solution that would primarily stop some of the erosion due to winds and seasonal high waters, but that would also provide an esthetically pleasing waterfront area, requiring little to no ongoing maintenance.

The solution implemented involved, surveying and grading the area, putting down an environmentally friendly shore liner and then securing it with a rock feature graded to allow for access to the water from the property.

## **Unique Project Challenges**

As with any project around water, one of the main factors that needed to be considered was the stability of the underlying shoreline, both over the long term and during construction. The equipment operator conducted testing throughout the project to ensure that the ground was and would remain stable.

Accessibility also proved to be a challenge, that was overcome with the use of smaller equipment, resulting in a little more time required to complete the project, but that ultimately reduced the damage as a result of it.

## **Highlights**

- An esthetically pleasing solution to an environmentally driven problem.
- Very satisfied property owners.

